# Weathertzation Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/90009MD1089/1
Work Order Type: Weatherization

Audit Name: Audit (39)

CL	IEI	٧T	IN	FΟ	RN	1A 1	ΓΙΟΝ

Client Name: Address:

Client ID: 90009MD1089

Alt. Client ID:

#### **AGENCY INFORMATION**

Agency: Metropolitan Development Housing Agency

Agency Phone:

Address: 701 South 6th Street

Fax:

Nashville, TN 37206 Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### <u>COMMENT</u>

### Measures

	all R-30 fiberglass batts access and ws with fo		е	Componen	ts			Inspecte
Comment								
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 2 Repl	lace Htg. System			Componen				Inspecte
# Material / Labor	Description / Comment	Unita	Otr.	Estimated		Ot+4	Actual	Total
	Description / Comment	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating Equipme	Replacement Furnace (not used) - 189 kBtu/h NG Existing, 24 - 33 kBtu/h NG Post	Edcii	1					
2 Labor	Replacement Furnace	Each	1					
	(not used) - 189 kBtu/h NG Existing, 24 - 33 kBtu/h NG Post							I
Other Detail			1	1		1	1	
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Work Order Name: WO/90009MD1089/1 Report Run On: 5/26/2010

Measure 3 User	r-Spec Ceiling R			Componen	ts A1			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	1448					
2 Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	1448					
Other Detail								
			Measure	e Sub Total:		] ;	Sub Total:	
Field Notes:							<u> </u>	
Measure 4 Wind	dow Sealing			Componen	7,WD WD3,	8,WD9	,WD5,	Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Window Sealing	Each Window	9					
2 Labor	Window Sealing	Each Window	9					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								

Measure 5 DW Comment	H Pipe Insulation			Componen	ts		1	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
						] []	Cub Totals	
			Measur	e Sub Total:		]	Sub Total:	
	art Thermostat			Componen	ts			Inspected
	art Thermostat			Componen Estimated			Actual	Inspected
Comment	art Thermostat  Description / Comment	Units	Qty	-		Qty		Inspected
Comment # Material / Labor	Description / Comment	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Comment  # Material / Labor  1 Heating Equipme	Description / Comment		_	Estimated		Qty	Actual	
Comment  # Material / Labor  1 Heating Equipme	Description / Comment Smart Thermostat	Each	1	Estimated		Qty	Actual	
# Material / Labor  Heating Equipme  Labor	Description / Comment Smart Thermostat	Each	1	Estimated		Qty	Actual	
# Material / Labor  Heating Equipme  Labor	Description / Comment Smart Thermostat	Each	1	Estimated		Qty	Actual	
# Material / Labor  Heating Equipme  Labor	Description / Comment Smart Thermostat	Each	1 1	Estimated			Actual	
# Material / Labor  Heating Equipme  Labor	Description / Comment Smart Thermostat	Each	1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor  1 Heating Equipme  2 Labor  Other Detail	Description / Comment Smart Thermostat	Each	1 1	Estimated Unit Cost			Actual Unit Cost	

Comment	H Tank Insulation			Componen	ts		,	Inspecte
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail						1		
						] []		
			Moscur	e Sub Total:		] []	Sub Total:	
Field Notes:			Weasur	e Sub Total.			oub rotur.	
	tion Detection				4- 1-74			Inanasta
_	nting Retrofits			Componen Estimated			Actual	Inspecte
Comment	nting Retrofits  Description / Comment	Units	Qty	-		Qty		Inspecte
Comment  # Material / Labor		<i>Units</i> Each Lamp	<b>Qty</b> 18	Estimated	1	Qty	Actual	
Comment  # Material / Labor  1 Lighting	Description / Comment	Each		Estimated	1	Qty	Actual	
Comment  # Material / Labor  1 Lighting	Description / Comment Compact Fl 13 Watt	Each Lamp Each	18	Estimated	1	Qty	Actual	
# Material / Labor  Lighting  Labor	Description / Comment Compact Fl 13 Watt	Each Lamp Each	18	Estimated	1	Qty	Actual	
# Material / Labor  Lighting  Labor	Description / Comment Compact Fl 13 Watt	Each Lamp Each	18	Estimated	1	Qty	Actual	
# Material / Labor  Lighting  Labor	Description / Comment Compact Fl 13 Watt	Each Lamp Each Lamp	18	Estimated	1		Actual	
# Material / Labor  Lighting  Labor	Description / Comment Compact Fl 13 Watt	Each Lamp Each Lamp	18	Estimated Unit Cost	1		Actual Unit Cost	
Comment  # Material / Labor  1 Lighting  2 Labor  Other Detail	Description / Comment Compact Fl 13 Watt	Each Lamp Each Lamp	18	Estimated Unit Cost	1		Actual Unit Cost	

Comment	II Insulation			Componen	nts WL1,\	NL2,W	′L3,WL4	Inspecte
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1856					
2 Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1856					
Other Detail						,		
			Measure	e Sub Total:		,	Sub Total:	
Measure 10 Flo								
Comment	or Ins. R-30			Componen				Inspected
Comment  # Material / Labor		Units		Estimated		Qty	Actual	Inspected
# Material / Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-30	<i>Units</i> SqFt	<b>Qty</b> 1454	•	<u> </u>	Qty		
# Material / Labor  1 Insulation	Description / Comment  Floor Insulation - Fiberglass Faced Batt - R-30  Floor Insulation - Fiberglass Faced Batt -		Qty	Estimated	<u> </u>	Qty	Actual	
# Material / Labor  1 Insulation  2 Labor	Description / Comment  Floor Insulation - Fiberglass Faced Batt - R-30  Floor Insulation -	SqFt	<b>Qty</b> 1454	Estimated	<u> </u>	Qty	Actual	
# Material / Labor  1 Insulation	Description / Comment  Floor Insulation - Fiberglass Faced Batt - R-30  Floor Insulation - Fiberglass Faced Batt -	SqFt	<b>Qty</b> 1454	Estimated	<u> </u>	Qty	Actual	
# Material / Labor  1 Insulation  2 Labor	Description / Comment  Floor Insulation - Fiberglass Faced Batt - R-30  Floor Insulation - Fiberglass Faced Batt -	SqFt	<b>Qty</b> 1454	Estimated	<u> </u>	Qty	Actual	
# Material / Labor  1 Insulation  2 Labor	Description / Comment  Floor Insulation - Fiberglass Faced Batt - R-30  Floor Insulation - Fiberglass Faced Batt -	SqFt	<b>Qty</b> 1454	Estimated	<u> </u>		Actual	

Page 6 of 10

1	Measure 11 CO N	Monitor is Needed			Componen	ts			Inspected
C	Comment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Mossur	e Sub Total:		] []	Sub Total:	
Г	Field Notes:			Measur	e Sub Tolai.			Jub Total.	
	Measure 12 Fix li	mproper Venting (Cloth	nes Dryer	)	Componen				Inspected
С	Comment				Estimated		Otv	Actual	
<i>C</i>		Description / Comment	nes Dryer <i>Units</i> Each	<b>Qty</b> 1	•		Qty		Inspected Total
<b>C</b> # 1	Comment  Material / Labor	Description / Comment	Units	Qty	Estimated		Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Equipment	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety	Description / Comment Equipment	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Equipment	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Equipment	Units Each Hour	<b>Qty</b> 1 1	Estimated			Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Equipment	Units Each Hour	<b>Qty</b> 1 1	Estimated Unit Cost			Actual Unit Cost	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor  Other Detail	Description / Comment Equipment	Units Each Hour	<b>Qty</b> 1 1	Estimated Unit Cost			Actual Unit Cost	

1	<i>Measur</i> e 13 Fix lı Fan	mproper Venting Kitch	en Exhau	st	Componen	its		1	Inspected
C	omment				Estimated	ı		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
					Onit Cost	I Olai	Qiy	Onit Cost	I Otal
1	Health and Safety	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
		mproper Venting of Ba aust Fan	throom		Componen			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety	-	Each	4 <i>iy</i>	Om Cost	Total	Qiy	Om Cost	Total
2	Labor	Labor	Hour	1					
C	Other Detail				1		1		
L									
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								

Report Run On: 5/26/2010

	nstall aerator showerhead			Componen	ts		1	nspecte
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Unspecified	Misc Material	Each	1					
•								
Other Detail								
			Measur	e Sub Total:		] .	Sub Total:	
Field Notes:								
Measure 16 S	eal all electric, plumbing a		ate	Componen	ts			nspect
Measure 16 S			ate	·				Inspecte
Measure 16 S	enetrations with caulk or t		ate	Componen  Estimated  Unit Cost		Qty	Actual Unit Cost	Inspecte
Measure 16 Sp Comment # Material / Labor	enetrations with caulk or t	foam ins.		Estimated	<u> </u>	Qty	Actual	
Measure 16 Sp Comment  # Material / Labor	enetrations with caulk or t  Description / Comment	foam ins. <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
Measure 16 S  Comment  Material / Labor  Unspecified	enetrations with caulk or t  Description / Comment	foam ins. <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
Measure 16 S  Comment  Material / Labor  Unspecified	enetrations with caulk or t  Description / Comment	foam ins. <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	

Report Run On: 5/26/2010

	Measure 17 Smo	ke Detector is Needed			Componer	nts			Inspected
C	omment								
ш.					Estimated	<del></del> -		Actual	<b></b>
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail			1					
L									
L				Moasur	e Sub Total:		]	Sub Total:	
Г	Field Notes:			Weasur	e Sub Total.				
	•	or Barrier Needed ement/CrawIspace)			Componer	nts			Inspected
					Estimated	<i>d</i>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	der Gra	and Total:		Gran	d Total:	